

All ten (10) cypress and marsh wetlands have four (4) marker stakes installed (i.e. wetland edge, NP -6", NP-12", and deep stake) except wetlands marked by asterisk where water was too deep to install deep stake.

Morris Bridge Wellfield:

Well Marsh

Lat. 28 07 31.4
Long. 82 19 09.8

X-4 Cypress

Lat. 28 07 24.7
Long. 82 20 11.3

Clay Gully Cypress

Lat. 28 07 19.6
Long. 82 20 45.6

South Cypress Marsh

Lat. 28 06 31.7
Long. 82 19 59.2

*** Trout Creek Marsh**

Lat. 28 06 41.2
Long. 82 21 36.5

"Deep" is staff gauge/recorder area.

MBR-30 Cypress

Lat. 28 06 24.4
Long. 82 20 16.2

Follow palmetto edge to fluorescent stakes.

West Cypress

Lat. 28 07 01.6
Long. 82 20 57.9

Follow marking tape flagging to north side of dome where transect starts.

X-1 Cypress

Lat. 28 07 08.6
Long. 82 21 11.9

MBR-11

Lat. 28 07 24.6
Long. 82 20 03.2

Lat. 28 08 49.5

Hillsborough River State Park Long. 82 13 41.5

*** Hillsborough River State Park Marsh** At entrance inform Park personnel that you are conducting "Test" wetland assessment for SWFWMD. From Park entrance follow paved roadway about 1 mile to Service Vehicle roadway (just past Parking Lot #2). Turn left on Service Vehicle roadway and go to back of Service Compound. Continue on 100-200 ft bearing right where dirt road splits. The Marsh is right behind the Service Compound. "Deep" area of the Marsh is Duck Potato area.



